


State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 12:120)

Date of Notification (1) 07/01/2016		Name of Building Owner/Operator (2) US Army Installation Management Command							
Agencies Notified <input checked="" type="checkbox"/> EPA <input type="checkbox"/> DEP <input type="checkbox"/> DOL <input type="checkbox"/> DOH <input type="checkbox"/> DCA	Type Notification <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Amended Amendment # _____ <input type="checkbox"/> Emergency (including justification) <input type="checkbox"/> Cancellation	Street Address Picatinny Arsenal							
		City, State, Zip Code Picatinny, NJ 07806							
		Name of Contact Danny Castellano	Telephone Number 973-724-4472						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Building B-45		Type of Facility (4) <input type="checkbox"/> School (K-12) <input type="checkbox"/> Subchapter 8 (Other than K-12) <input checked="" type="checkbox"/> Other (i.e. private & commercial buildings, homes, etc.)							
Street Address Picatinny Arsenal		Square Feet 4500	# of Floors 1						
City (5) Picatinny		Bldg. Age 50+							
County (6) Morris	County Code (7) (STATE USE ONLY) _____	Current Use (Prior if being demolished) Warehouse							
Name of Monitoring Firm Hired by Building Owner (8) N/A		ASCM No. _____	Name of Abatement Contractor (9) Bako Construction & Restoration, Inc.						
Street Address		Street Address 265 A Route 46 Suite 3D							
City, State, Zip Code		City, State, Zip Code Totowa, NJ 07512							
Project Manager for Monitoring Firm	Telephone No. _____	Telephone No. 973-256-7010	License No. 0666						
Start Date (10) 08/01/2016	Scheduled Completion Date (11) 08/10/2016	Name of OSHA Monitor Bako Construction & Restoration, Inc.							
Occupancy Status During Abatement (Check Only One) <input checked="" type="checkbox"/> Facility Closed/Vacated During Entire Period of Abatement <input type="checkbox"/> Abatement Performed Outside of Normal Facility Hours <input type="checkbox"/> Other - Describe: _____		Street Address 265 A Route 46 Suite 3D							
		City, State, Zip Code Totowa, NJ 07512							
Scope of Work (Check All That Apply)									
<input type="checkbox"/> ≥ 3 sf or ≥ 3 lf <input checked="" type="checkbox"/> ≥ 160 sf or ≥ 260 lf		<input checked="" type="checkbox"/> Renovation <input type="checkbox"/> Demolition							
		<input type="checkbox"/> Full Containment with Negative Pressure <input type="checkbox"/> Mini-Enclosure <input type="checkbox"/> Glovebag Procedure <input checked="" type="checkbox"/> Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> In Facility (13)	Is Location Normally Used Solely by Maintenance/ Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e. thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Building B-45		X		Asbestos Roof Panels	4500 SF	X			
Name of Registered Waste Hauler Bako Construction & Restoration, Inc.		NJDEP Waste Hauler ID No. 20889	Cubic Yards of Waste 50	Name of Registered Landfill Tullytown Resource Recovery Facility					
City, State Totowa, NJ		Disposal Date 08/10/16		City, State Tullytown, NJ					
Completed by Damir Valjevac		Title Project Manager		Signature 			Date 07/01/2016		